Turbo Model/ Application	Proturbo Turbocharger Core acceptance policy		
	Full Credit Criteria	Deduction	No Credit
Cummins VGT Air or Electronic Actuated	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Heavily damaged wheels and/or shaft (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) Turbine Wheel Separation (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part Disassembled
Caterpillar (Ball Bearing) Models	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models, must have CAT logo 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Heavily damaged wheels and/or shaft (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) Turbine Wheel Separation (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part Disassembled
Caterpillar (Standard Turbocharger) 704604-9007, 704604-9011)	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like, must have CAT or Garrett logo. 4 Support Webs 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Heavily damaged wheels and/or shaft (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) Turbine Wheel Separation (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Turbo with 3 support Webs Part Disassembled
Detroit Diesel VGT	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Heavily damaged wheels and/or shaft (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) Turbine Wheel Separation (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part Disassembled

Proturbo LLC | 1-877-234-3897 | https://www.proturbo.us

_	1		4/15/2021
VOLVO VGT MODELS	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Heavily damaged wheels and/or shaft (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50%Deduction) Turbine Wheel Separation (50%Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part Disassembled
Ford 6.4 Powerstroke	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Damaged VGT cage due to turbine wheel explosion (50%) Missing Clamps (25% Deduction) Missing Parts or Actuators (50%Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part disassembled
Ford 6.7 Powerstroke	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged VGT cage due to turbine wheel explosion (50%) Missing Clamps (25% Deduction) Missing Parts or Actuators (50%Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part disassembled
Dodge Cummins 6.7 HE351VG/HE300VG	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part disassembled
Standard Turbochargers (All Models, Non VGT)	 All components present and assembled. Like for like models On Vehicle damage to compressor and turbine housing. On Vehicle damage due to Compressor & Turbine Wheel. 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50% Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part disassembled
Other VGT Models (Paccar, Hino, Nissan, etc)	 All components present and assembled. Light or minimal damage to compressor and turbine housing. Light or minimal damaged to Compressor & Turbine Wheel. Like for like models 	 Cracked or Damaged due to freight (50-100%) Damaged Electronics (50% Deduction) Heavily damaged wheels and/or shaft (50% Deduction) Missing Clamps (25% Deduction) Missing Parts or Actuators (50%Deduction) Turbine Wheel Separation (50%Deduction) 	 Excessive Rust or water damage Fire Damage Knock Off Models (Not Genuine) Part Disassembled

Freight and Removal damage are not covered. Ensure you packaged the core sufficiently!

| 1-877-234-3897 |